


Possible Compressor Operating Range



Point	P1	P2	P3	P4	P5	P6	P7	P8
Evaporating Temperature(°C)	15	6	-20	-20	-1	15	3	-7
Condensing Temperature(°C)	64	64	45	30	30	49	64	64

Point	P9	P10	P11	P12	P13	P14	P15	P16
Evaporating Temperature(°C)	-25	-37	-37	-20	-20	-25	-25	15
Condensing Temperature(°C)	46	26	2	10	21	21	30	30